


Benson

|    | Type | Hits | Search Text   |
|----|------|------|---|
| 1  | BRS  | 110  | S1 and resist\$4  |
| 2  | BRS  | 3    | S3 with arc same gap  |
| 3  | BRS  | 8    | S3 and arc same gap   |
| 4  | BRS  | 442  | high adj tension adj circuit  |
| 5  | BRS  | 32   | S3 and test   |
| 6  | BRS  | 38   | arc adj fault adj test  |
| 7  | BRS  | 2169 | arc and (spark adj gap)   |
| 8  | BRS  | 839  | arc with (spark adj gap)  |
| 9  | BRS  | 135  | S9 and test   |
| 10 | BRS  | 0    | S10 and ignt\$4   |
| 11 | BRS  | 48   | S10 and ignit\$4  |
| 12 | BRS  | 1845 | igniter and test  |
| 13 | BRS  | 271  | S13 and arc   |
| 14 | BRS  | 6    | igniter with test same arc  |
| 15 | BRS  | 2    | "6680614"   |
| 16 | BRS  | 9    | high adj voltage with arc with gap with test  |
| 17 | BRS  | 165  | corrosion adj probe   |
| 18 | BRS  | 565  | "4488939" "4882537" "5232667" "4356406" "4423434" "6095679"<br>"6208128" "4032881" "4056887" "4282423" "4436438" "4458137"<br>"4558456" "4575705" "4586246" "4800292" "4838296" "5024106"<br>"5317343" "5464965" "5541564" "5599295" "5720718" "5726624"<br>"5729653" "5999096" "6056699" "6076963" "6085575" "6107798"<br>"6394784" "6411192" "4914417" "5797964" "4150562" "4262532"<br>"4272753" "4333068" "4412203" "4424507" "4451753" "4485319"<br>"4822465" "4827769" "4911011" "4922083" "4960125" "4982599"<br>"5004190" "5234837" |
| 19 | BRS  | 196  | S18 and probe   |
| 20 | BRS  | 26   | S20 and hollow  |



Creation date: 02-14-2005

Indexing Officer: FGONZALEZ - FRANCISCO GONZALEZ

Team: 2800PrintWorkingFolder

Dossier: 10471152

Legal Date: 02-10-2005

| No. | Doccode | Number of pages |
|-----|---------|-----------------|
| 1   | CTNF    | 6               |
| 2   | 1449    | 2               |
| 3   | 892     | 1               |
| 4   | FWCLM   | 1               |
| 5   | SRFW    | 1               |
| 6   | BIB     | 1               |

Total number of pages: 12

Remarks:

Order of re-scan issued on .....